

CHANGE 3.18

1. Supersedure notice <wpsupersede> is deleted from the DTD per MIL-STD-40051 -1/-2 Change2.
2. Supersedure notice <wpsupersede> is deleted from <wpidinfo> per MIL-STD-40051 -1/-2 Change2.
3. NOTICE the agreed changes for Illustrated List of Manufactured WP was not correctly annotated. The elements <manuwp> and <manfcprocwp> in MIL-STD-40051-1/2 Change 2 were agreed as elements <manu_items_introwp> and <manuwp>.
4. The element <production> has been changed to include the Publication Identification Number (PIN) IAW MIL-STD-40051-2 change 2. The PIN will be included on the back cover graphic (para 5.2.2.7) and authentication page graphic for change transmittal package (para 4.8.1.1).
5. The element <production> has been changed to include the BDAR manual.
6. Adding the MIL-STD-40051-1/2 Change 2 Appendix I BDAR information. Includes the following elements <baim>, <bdar>, <bdarcategory>, <bdar-combat-threat>, <bdar-fixes>, <bdar-geninfowp>, <bdar-limitation>, <bdar-mtrl-tools>, <bdar-persn>, <bdar-persn-item>, <bdar-repair>, <bdar-repair-option>, <bdar-repair-proc>, <bdar-std-practices>, <bdar-task-resp>, <bdartoolswp>, <bgim>, <bim>, <brim>, <damage-assesswp>, <genrepairwp>, <substitute-matwp>
7. The element <paper.manual> was changed to add an optional BDAR chapter. This supports the specific system BDAR requirements found in MIL-STD-40051-2 Notice 2.
8. The element <paper.manual> was changed to add volume breaks for dim, pim, and bim.
9. The element <functionhierarchy> and <systemhierarchy> was changed to add an optional BDAR chapter. This supports the specific system BDAR requirements found in MIL-STD-40051-1 Notice 2.